Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: FOLVAG 5-8 4TFH

Field Name: STONY CREEK Well File #: 24183

Date Incident:2/23/2016Time Incident:11:30Facility ID Number:County:WILLIAMSTwp: 156Rng: 100Sec: 32Qtr:

Location Description: Well- Site Facility

Submitted By: Stephen Sypult Received By:

Contact Person: Jim Haugen

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Spilled Units Recovered Units Followup Units

Oil 3 Barrels 3 Barrels

Brine

Other

Description of Other Released Contaminant:

Crude Oil

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Limited risk as fresh water was holding pressure and minimal crude was allowed to spill. The line was isolated and the check valve was removed.

Areal Extent:

Spill was contained on location next to the wellhead.

Potential Environmental Impacts:

Localized soil impacts contained to immediate area around the wellhead.

Action Taken or Planned:

Removed check valve and install new check valve. Establish PM for check valves based on manufacturer's recommendation for residual life.

Wastes Disposal Location: Phillips and Jordan cleaned the waste and will take it to our approved

waste facility.

Agencies Involved:

Updates

Date: 2/24/2016 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.